

WWRA OPS COMMITTEE TASK TRACKING (28 September 2003 to 16 March 2004)**CURRENT PRIORITY ACTION ITEM – ACTION ITEM – INDEFINITE HOLD – COMPLETED ITEM**

20032 004	Task	Order Status	Op Status	Work	Equipment	REMARKS	B G J	Target Due Date
9/28	03163	-	-	Procure SERVICE MONITOR from Joe, W7COM already approved by the Board. Awaiting Joe to come up with documentation.	Service Monitor	Joe needs to develop training manual and obtain technical manual for Motorola Service Monitor.	J	TBD
9/30	03164	-	-	Encode PL on UHF so that it follows the carrier on which will allow it to be IRLP Compliant. Joe needs to manufacture tone encoder for easy plug into Port 1 of RLC 2.	IRLP	INTERNET REPEATER LINK PROJECT	J	TBD
9/30	03165	-	-	Procure copper plate and install for central grounding point.	Repeater Grounding	Repeater is grounded with heavy-duty copper cable in generator room.	J G	CANCELLED NOT NEEDED
12/2	03167	Ordered 11/30 Rcvd 12/2	Yes	Mount Mic E and weather station equipment to slide-in/out shelf. Installed 2/15/04 but not hooked up until completion of RLC Club programming.	Mic E & Weather Station		G	Hill Trip COMPLETED 3/1/04
12/2	03168	-	No	Reset Barometer's on APRS and Weather Vox	Weather Station		G	Completed February 4, 2004
1/15	04170	Ordered 12/28 Received 1/23	No	New RLC Club controller to replace RLC 2 controller. The Club controller requires time to program such items as speed dials in addition to learning the new capabilities.	RLC Club Controller		J G B	COMPLETED 28 February 2004
1/19	04171	Related to Task 03165	No	Install new 7-½ foot cabinetry.	Cabinet		G J	TBD
2/15	04172	-	-	1. Repaired UHF transmitter. 2. Installed Polyphaser telephone grounding block.	UHF	Joe, W7COM and George, N7GME made trip to hill to conduct emergency repair to UHF.	G J	Completed February 15, 2004
3/2/04	04173	-	No	Troubleshooting RLC Club programming	MIC		G	Hill trip 3/2/04
3/3/04	04174	-	No	Removed UHF repeater and RLC Club controller from hill for troubleshooting	RLC Club Controller	Returned UHF repeater and RLC Club controller from hill after troubleshooting	G G	(2) Hill trips 3/3/04
3/5/04	04175	-	No	Adjusted audio levels on ports 2 and port 3. Little more grooming of controller is needed.	RLC Club Controller	Put regular VHF repeater online. Entire system up and running.	G	Hill trip 3/5/04
3/8/04	04177	-	Yes	Adjusted tone levels on UHF and VHF transmitters.	UHF & VHF		G	Completed 3/8/04
3/8/04	04178	-	Yes	Adjusted audio levels for phone patch.	Auto-patch	Working 3/15/04 for low-level users with security installed.	G J B	Hill trip Completed 3/8/04
3/9/04	04179	-	Yes	Programmed RLC Club Deluxe II to allow auto-patch operations by users.	Auto-patch	Working 3/15/04 for low-level users with security installed.	G B	Completed 3/9/04
3/11/04	04180	-	-	Echolink operational but needs further programming. Bill, N7YT programmed 3/12/04.	Echolink	Working for all users 3/12/04	B	Completed 3/12/04

20032 004	Task	Order Status	Op Status	Work	Equipment	REMARKS	B G J	Target Due Date
3/17/04	04181	Ordered 3/17/04 Received	No	<p>Hill trip to bring down DVR 1 for maintenance and or repair. Has to re-wire before returning to hill. George, N7GME working on:</p> <ol style="list-style-type: none"> 1. Replacing DVR -1 backup battery. 2. Programming DVR <ol style="list-style-type: none"> a. 9600/8/N/1 b. Set DVR modem upload ASC II settings to 8ms line delay and 1 ms character delay. 3. Got DVR working on 3/16/04. 4. Programmed sound files back into the DVR-1 5. Got DVR responding utilizing RLC 2 on 3/19/04. 	DVR-1	<p>Ordered replacement Ni-cad battery #7435A 6 3/8" x 2 1/2" x 3/4" W&W Manufacturing 800-221-0732 WC-039-7435A 12.5 volts \$42.70 INCL Shipping Note: DVR lost four programs that were uploaded before bringing up to mountain. Power cord and installed battery didn't retain these uploads. Must upload on mountain to ensure retention of programming.</p>	G	<p>COMPLETED 4/1/04 Reinstalled on Gold Mountain 4/30/04 until DVR 8 is ready</p>
3/17/04	04182	Related to Task 04176		<p>Wx Vox Recovered from hill on 3/17/04 Will be installed next hill trip.</p>	WX VOX	<p>Bill, N7YT Bill completed wiring harness on 27 March.</p>	G B	<p>COMPLETED 4/30/04</p>
3/18/04	04183	-	Yes	<p>Build Signal Generator circuit to have the capability to test controller and DVR without use of repeater hooked up.</p>	DVR-1 Controller Testing	<p>This project ultimately was cancelled for the DVR 1 but completed for the DVR 8.</p>	G	<p>COMPLETED 4/15/04</p>