

WWRA OPS COMMITTEE TASK TRACKING (6 December 2001 to 6 July 2002)**CURRENT PRIORITY ACTION ITEM – ACTION ITEM--INDEFINITE HOLD – COMPLETED ITEM**

2001-2002	Task	Order Status	Op Status	Work	Equipment	REMARKS	P B G	Target Due Date
12/6	0181	Related to Task 0176	-	Bill and George to work on getting cable pressure tested and connectors installed.	Antennae	Bill procured straps on 6/21 for install of new coax.	B G	COMPLETED 23 June
01/28	0299	No	No	Procured air filled @ \$0.00 per foot coax to replace our current coax to the high VHF antenna. Bill and George checked VSWR on 3 May 02. Checked out okay. We are going with this.	VHF	There are several possibilities for running coax up the tower. This will give us one NEW coax for VHF. The old air filled for UHF. With two coax it gives us the option of shifting to one coax for both antennae in case of failure of one.	B G	COMPLETED 3 MAY
04/06	02117	Ordered 04/22 Received 6/4	Yes	Order complete new VHF receiver/transmitter repeater to be married to RLC 2 controller. We are going to remove old VHF controller and repeater for emergency backup.	VHF	Since a new myriad of problems arose in hooking up UHF repeater with RLC 2 it has been decided to procure new VHF equipment.	G	COMPLETED 6/4
06/12	02128	Related to Tasks 02123 & 02124	No	Replace 15ohm ¼ watt resistors and 1/16 amp Pico resistors in telephone circuit. Installing Polyphase black boxes in telephone line before controller.	UHF Auto patch	George returned RLC2 to hill and re-programmed auto patch features to match up with VHF auto dial.	B G	HILL TRIP COMPLETED 21 JUNE
06/21	02131	Related to Task 02128	No	Microphone Encoder not working. Needs too be checked next trip to hill.	Microphon e Encoder		B G	COMPLETED
06/23	02133	Ordered 21 June Received 27 June	-	Procure T connector for desiccant pump for second coax.	Second Coax		G	COMPLETED 27 JUNE
06/23	02134	Related to Task 02133	No	Install airline to second coax.	Second Coax	CANCELLED because second coax was determined to be foam filled.	B G	CANCELLED
06/23	02135	Ordered 24 June Received 26 June	-	Radio Dave drop shipping RG-214 cable connectors to Bills office to enable us to manufacture new cabinet cabling. Current cabling have bad crimps.	Cabinet Cabling		B G	COMPLETED 25 JUNE
06/24	02136	Ordered 24 June Received 26 June	-	George ordered two double female N connectors.	Second Coax		G	COMPLETED 26 JUNE
06/24	02137	-	-	George reversed cabling in KPC 9612 inputs in Ports 1 & 3. On 30 June set CD to Internal/Internal/Software.	KPC 9612		G	COMPLETED 25 JUNE
06/25	02138	-	-	George removed Low Pressure gauge on Nitrogen flask to repair.	Dehydrator System		G	Hill Trip 25 JUNE COMPLETED

2001-2002	Task	Order Status	Op Status	Work	Equipment	REMARKS	P B G	Target Due Date
06/26	02139	-	-	George reprogrammed KPC 9612.	KPC 9612		G	Hill Trip 26 JUNE COMPLETED
06/26	02140	-	-	George repaired and returned Low Pressure Gauge to Nitrogen bottle.	Dehydrator System		G	Hill Trip 26 JUNE COMPLETED
07/06	02141	Related to Task 02130	-	Bill and George took modem up to hill to install with RLC-2. It was getting some data responses that looked like the wrong baud rate. Brought it back down to try brainstorming the problem.	Controller Modem	Appears to be settings. Schedule another hill trip.	B G	Hill Trip 6 JULY COMPLETED